

Choose

URETEK™

QUICK, CLEAN, ECONOMICAL SOLUTION
to lift, realign, and stabilize
sinking pools and trip hazards.

pH may not be the only thing out of balance.

- 6 IN.

URETEK

ICR™

URETEK™

Concrete Lifting and Soil Stabilization
for Sinking Pools and Natatoriums

SYMPTOMS

Pool Settlement and Soil Erosion

Uneven Pool Water Level

Soil erosion, poor soil compaction, leaky pool equipment are all culprits to a pool sinking and becoming unbalanced.

ENVIRONMENTAL



URETEK's patented polymers are continually tested for maximum quality and performance.

URETEK materials continually exceed environmental standards and requirements and is safe to install around people, pets, and plants. URETEK materials are NSF 61 certified, completely safe to inject around community drinking water systems.



"I love your product, it resolves the problem with no disruption."

- Carolyn Jeffus

Leaky or Poorly Maintained Equipment

A pool that is out of balance can cause costly damage to pool equipment as well as the structural condition of the pool body itself. Problematic wash-outs and soaked soil eventually will lead to pool settlement

Uneven Concrete Decking

Sunken and uneven concrete decking is not only annoying and unsightly, but is a liability concern for your family or community pool as a trip hazard.

SOLUTIONS

Pool Lifting and Soil Stabilization

URETEK's expanding polyurethane grout was specifically developed to lift, stabilize, and compact loose base soils under sunken structures. The rapid curing expanding polyurethane grout accurately realigns un-even pools quickly, with most repairs completed in a day with a long lasting result so you can enjoy your pool right away, without a messy repair process.

Many newer pools are under warranty from the builder. Request URETEK as a repair solution. Check with your insurance carrier about using URETEK as an alternative solution to realign uneven concrete decking.



800.240.7868
www.LIFTCONCRETE.com

Why **URETEK**?

URETEK's expanding polyurethane rapidly expands as it is injected under the pool. Weak soil is compacted by the expanding foam, increasing the load bearing capacity of the soil. After the soil is compacted, URETEK polymer gently lifts the pool structure back to acceptable tolerance so you can enjoy your pool quicker, without a costly, messy repair process.



4 FT.



URETEK[™]
QUICK, CLEAN, ECONOMICAL SOLUTION
to lift, realign, and stabilize
sinking pools and trip hazards.

URETEK's quick,
clean, pool lifting and
stabilization process
will have you enjoying
your pool faster.

URETEK's rapid expanding
polyurethane stabilizes eroded
soil and fills voids causing your
pool to sink. After the soil is strengthened by the
expanding foam, your pool is carefully realigned as
URETEK's expanding foam gently raises your pool to
an acceptable level.

URETEK

ICR

ANSI

TRIA

NSC

NSF

Boat Manufacturer

800.240.7868
WWW.LIFTMYPPOOL.COM